

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer SIBIN.S
2. Name of the School CHRIST NAGAR CENTRAL SCHOOL
3. Location with name of Education District/Sub. District Kattakada
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.  
BLOCK-I  
① 37.00 m x 8.45 m x 3.70 m - GRP P.P. CRCC  
BLOCK-II  
① 35.90 x 10.45 m x 3.70 m - GRP P.P. ST  
② 9.70 x 5.75 m x 3.70 m - P.P. & ST  
③ 54.55 x 9.90 x 3.70 m - P.P. & ST } CRCC Post  
BLOCK-III  
① 35.10 x 10.20 x 3.70 m - Cellar  
BLOCK-III Toilet  
① 8.40 m x 4.80 m x 3.00 m - GRP P.P. CRCC
5. Period for which the certificate is issued 2020-21
6. Nature of defects, if any  
a) Foundation and basement  
b) Superstructure  
c) Doors and Windows  
d) Wood work wrought and put up  
e) Roof  
f) Flooring  
g) Miscellaneous (Cracks, etc.)  
Nil
7. Any major defects noticed which will render the building unsafe in any manner  
Nil
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes Sound under normal weather and wind condition


**Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on 02/03/2020 and found to be fit / unfit to conduct classes, for the period 2020-21 for the reasons stated above.

Place : Kattakada

Date : 02/03/2020



S. S. S. S.  
ASSISTANT ENGINEER  
S.G.D. Section  
Kattakada Grama Panchayat  
Kattakada P.O.